Amy Ow

From: Jessica Henderson-McBean < JHenderson-McBean@swca.com>

Sent: Wednesday, October 14, 2020 4:09 PM

To: Camille Leung

Cc: Kristen Outten; Amy Ow

Subject: Highland Estates Inspection Report - 10/14/2020

Attachments: Inspection_Report_Form_10.14.20.pdf

CAUTION: This email originated from outside of San Mateo County. Unless you recognize the sender's email address and know the content is safe, do not click links, open attachments or reply.

Hi Camille,

Please find attached my inspection report from today's site visit to Highland Estates. I noted the below action items that still need to be addressed from last week's visit.

Thanks!

Jessie Henderson-McBean

Project Manager / Biologist

SWCA Environmental Consultants

60 Stone Pine Road, Suite 100 Half Moon Bay, CA 94019 P 650.440.4160 x 6410| C 805.712.8794



Visit Our New Website!

The contents of this email and any associated emails, information, and attachments are CONFIDENTIAL. Use or disclosure without sender's authorization is prohibited. If you are not an authorized recipient, please notify the sender and then immediately delete the email and any attachments.

From: Jessica Henderson-McBean

Sent: Wednesday, October 14, 2020 4:00 PM

To: robertpellegrine@yahoo.com

Cc: Bob Pellegrine <Bob.P@nexgenbuilders.com>; Noel Chamberlain <noel@nexgenbuilders.com>; Kristen Outten

<koutten@swca.com>; Amy Ow <aow@smcgov.org>; cleung@smcgov.org

Subject: Highland Estates Site Visit - 10/14/2020

Hi Bob,

Sorry I missed you onsite today. I noted that there are still quite a few outstanding items that we had discussed last week.

Please address the following action items ASAP:

Lots 9/10

- Please remove the staged lumber from the sidewalk on Cobblehill Place. We need to keep all construction materials within the approved work area.
- Please install the drain inlet protection that Neil had previously discussed with you. Now that we are in the wet season, drain inlet protection is required by the SWPPP.

Lot 11

- Please key in the silt fence on the southeast side of Lot 11 per the requirements of the SWPPP.
- The chain link fence on the south side of Lot 11 had been opened up, and was laying on the ground. This fencing needs to stay in place at all times to protect the riparian area along the south side of Lot 11.
- The windbreak had fallen down on the north side of Lot 11. Please repair the windbreak and ensure that it remains in place throughout the duration of grading activities on Lot 11.

Please feel free to give me a call if you would like to discuss any of these items!

Thanks!

Jessie Henderson-McBean Project Manager / Biologist

SWCA Environmental Consultants 60 Stone Pine Road, Suite 100 Half Moon Bay, CA 94019 P 650.440.4160 x 6410 C 805.712.8794



Visit Our New Website!

The contents of this email and any associated emails, information, and attachments are CONFIDENTIAL. Use or disclosure without sender's authorization is prohibited. If you are not an authorized recipient, please notify the sender and then immediately delete the email and any attachments.